

SHOWER CREAM

RASPBERRY BUTTER, ZENIBERRY R-XX, ZENIBEE CREAM

	PHASE	INGREDIENT	FUNCTION	% BY WEIGHT	BATCH SIZE 1000.00
1.	A	Water	Diluent	37.15	371.50
2.	A	Disodium EDTA	Chelating Agent	0.10	1.00
3.	A	Dehydroxanthan	Thickening Agent	0.75	7.50
4.	A	ZENIBERRY R-XX (PEG-8 DIMETHICONE AND PEG-8 RASPBERRIATE)	Skin Feel	2.00	20.00
5.	B	Sodium Laureth Sulfate	Surfactant	30.00	300.00
6.	C	Cocamidopropyl Betaine	Surfactant	7.00	70.00
7.	D	Cocamide Mea	Viscosity	2.00	20.00
8.	D	Dihydrogenated Tallow Phthalic Acid Amide	Emulsifier	3.00	30.00
9.	D	Glycol Stearate and Stearamide Amp	Co-Emulsifier Pearlizing Agent	2.00	20.00
10.	D	RASPBERRY BUTTER (OCTYLDODECANOL, BEESWAX, RUBUS IDAEUS)	Skin Feel	10.00	100.00
11.	D	ZENIBEE CREAM (OCTYLDODECANOL, BEESWAX)	Skin Feel	5.00	50.00
12.	E	Fragrance	Fragrance	0.40	4.00
13.	F	DMDM Hydantoin	Preservative	0.25	2.50
14.	G	Sodium Hydroxide 20% Soln	pH Adjuster (5.5-6.5)	0.35	3.50
		Total		100.00	1000.00

Manufacturing instructions:

Heat phase A to 75°C. Add Phases B and C. Heat Phase D to 75°C and add to batch.

Cool to 40°C and add phases E, F and G. Adjust pH to 5.5-6.5.

Adjust Viscosity to 5,000-8,000CPS with NH4CL soln if necessary.

Formula Courtesy of



The above information is believed to be accurate and is offered in good faith and for the benefit of the customer. Zenitech, however, cannot assume any liability or risk involved in the use of its products since conditions are beyond our control. Statements concerning the possible use of our products are not intended as recommendations in the infringement of any patent. These products are for commercial use only.

08/30/2005